



**Location:** 1

**NGR:** TF 14528 47399

**Photo Date:** 13 July 2023

**Description:** Hodge Dike, with overgrown vegetation throughout bank, left bank c.2m, right bank c.2m, width c.5m, depth c.0.3m facing West



**Location:** 2

**NGR:** TF 14359 47250

**Photo Date:** 13 July 2023

**Description:** Unnamed reservoir, facing south.





**Location:** 3

**NGR:** TF 14317 47190

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout bank, left bank c.1m, right bank c.1m, width c.1.5m. Facing south



**Location:** 4

**NGR:** TF 14330 47155

**Photo Date:** 13 July 2023

**Description:** Footbridge. Facing West





**Location:** 5

**NGR:** TF 14317 47190

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing northwest



**Location:** 6

**NGR:** TF 14081 46771

**Photo Date:** 13 July 2023

**Description:** Unnamed drain (dry), with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing west



**Location:** 7

**NGR:** TF 14884 47447

**Photo Date:** 13 July 2023

**Description:** North side of unnamed drain, with a hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.



**Location:** 8

**NGR:** TF 14884 47447

**Photo Date:** 13 July 2023

**Description:** Same unnamed drain as 7. Passing place. Facing southeast.





**Location:** 9

**NGR:** TF 14884 47447

**Photo Date:** 13 July 2023

**Description:** South side of unnamed drain, with a hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.



**Location:** 10

**NGR:** TF 15216 47606

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with a hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.





**Location:** 11  
**NGR:** TF 15190 47698  
**Photo Date:** 13 July 2023  
**Description:** Unnamed drain, with a hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.



**Location:** 12  
**NGR:** TF 15111 47772  
**Photo Date:** 13 July 2023  
**Description:** Hodge Dike, overgrown vegetation throughout channel, left bank c.2m, right bank c.2m, width c.5m, channel c.0.3m. Facing north.





**Location:** 13  
**NGR:** TF 15512 48030  
**Photo Date:** 13 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing south.



**Location:** 14  
**NGR:** TF 15817 48268  
**Photo Date:** 13 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing west.



**Location:** 15

**NGR:** TF 15889 48291

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m, Channel c.0.3m no visible flow, no passing place. Facing south.



**Location:** 16

**NGR:** TF 15944 48332

**Photo Date:** 13 July 2023

**Description:** Pumping station at Hodge Dike, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m, channel c.0.3m, no visible flow. Facing northeast.





**Location:** 17

**NGR:** TF 13888 47177

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing west.



**Location:** 18

**NGR:** TF 13888 47177

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing south.





**Location:** 19

**NGR:** TF 13906 47239

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.



**Location:** 20

**NGR:** TF 14294 47454

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, connecting to Hodge Dike by the reservoir, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.3m. facing south.





**Location:** 21  
**NGR:** TF 14294 47454

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.3m. Facing north.



**Location:** 22  
**NGR:** TF 14171 47886

**Photo Date:** 13 July 2023

**Description:** Passing place over unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.3m. Facing north.





**Location:** 23  
**NGR:** TF 14267 47521

**Photo Date:** 13 July 2023

**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing west.



**Location:** 24  
**NGR:** TF 13657 48344

**Photo Date:** 14 July 2023

**Description:** unnamed drain, with overgrown vegetation throughout channel, left bank c.1m, right bank c.1m, width c.2m. Facing west.





**Location:** 25

**NGR:** TF 13746 48367

**Photo Date:** 14 July 2023

**Description:** Unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing southeast.



**Location:** 26

**NGR:** TF 13793 48313

**Photo Date:** 14 July 2023

**Description:** Passing place over unnamed drain, width c.3m. Facing east.





**Location:** 27  
**NGR:** TF 14140 48279  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.



**Location:** 28  
**NGR:** TF 14133 48209  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing north.





**Location:** 29  
**NGR:** TF 14481 48557  
**Photo Date:** 14 July 2023  
**Description:** Passing place over unnamed drain, width c.3m. Facing west.



**Location:** 30  
**NGR:** TF 14481 48557  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.4m. Facing north.





**Location:** 31  
**NGR:** TF 14539 48488  
**Photo Date:** 14 July 2023  
**Description:** Passing place and unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.4m. Facing southeast.



**Location:** 32  
**NGR:** TF 14548 48477  
**Photo Date:** 14 July 2023  
**Description:** Passing place. Facing northwest.





**Location:** 33  
**NGR:** TF 14567 48495  
**Photo Date:** 14 July 2023  
**Description:** Passing place. Facing southeast.



**Location:** 34  
**NGR:** TF 14481 48557  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.4m. facing east.





**Location:** 35  
**NGR:** TF 15050 48856  
**Photo Date:** 14 July 2023  
**Description:** Passing place. Facing south.



**Location:** 36  
**NGR:** TF 15218 48969  
**Photo Date:** 14 July 2023  
**Description:** Passing place adjacent to unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.3m. Facing east.





**Location:** 37  
**NGR:** TF 15218 48969  
**Photo Date:** 14 July 2023  
**Description:** Passing place and unnamed drain, with hedge and overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing north.



**Location:** 38  
**NGR:** TF 15149 49098  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.4m. Facing west.





**Location:** 39  
**NGR:** TF 15070 49249  
**Photo Date:** 14 July 2023  
**Description:** Passing place, width c.3m. Facing northeast.



**Location:** 40  
**NGR:** TF 15041 49314  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1.5m, right bank c.1.5m, width c.2m. Facing east.





**Location:** 41  
**NGR:** TF 15070 49249  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1m, right bank c.1m, width c.3m. Facing west.



**Location:** 42  
**NGR:** TF 14977 49425  
**Photo Date:** 14 July 2023  
**Description:** Unnamed drain, with overgrown vegetation throughout channel, left bank c.1m, right bank c.1m, width c.3m. Facing east.